

ALBERNI-CLAYOQUOT REGIONAL DISTRICT Parks Linear Asset Assessment & Mapping Grappler St. Wharf



July 29, 2025

Prepared for:

Alberni-Clayoquot Regional District
3008 Fifth Avenue
Port Alberni, BC
V9Y 2E3

Prepared by:

Herold Engineering Limited
Unit 7, 1920 Lyche Road
Ucluelet, BC
V0R 3A0

Attention: Amy Mayo, Asset Management &
Grants Coordinator



PARKS LINEAR ASSET ASSESSMENT & MAPPING

GRAPPLER ST. WHARF, BAMFIELD, BC

Prepared for:

Alberni-Clayoquot Regional District (ACRD)
3008 Fifth Avenue
Port Alberni, BC
V9Y 2E3

Attn: Amy Mayo, Asset Management & Grants Coordinator

Prepared by:

Herold Engineering Limited
Unit 7, 1920 Lyche Road
Ucluelet, BC
V0R 3A0

Submittal Date: July 29, 2025

Herold Project No.: 6516-001

Prepared by:

Reviewed by:



PERMIT TO PRACTICE: 1000201

Shannon Summersides, P. Eng.
Associate, Project Engineer

Jeff Duncan, P. Eng.
Associate

EXECUTIVE SUMMARY

The scope of the assignment includes assessment of the Grappler St. marine infrastructure located on the eastern side of Bamfield, British Columbia. The infrastructure is comprised of a fixed timber approach structure, steel truss gangway, a boathouse float, and several treated timber walkway floats. It is understood that half the floats (Float A, B, C, and D) are provided for public use by the ACRD. Float H and floats used to access the boathouse from Float D are utilized and maintained by the local Fire Department. Refer to Figure 2 in Section 2.3 for general arrangement of the floats.

The assessment was conducted on January 27, 2025, and included visual and tactile review of the components from above water only. The purpose of the assessment was to document the overall physical condition of the approach, gangway and floating structure via visual and tactile on-site assessment. The report includes detailed descriptions of the construction, findings of the assessment, recommended repairs/upgrades, risk analysis and Class D cost estimates for the recommended repairs and full replacement of the structure(s) in kind.

It is to be noted that the assessment was conducted from above water only. It is recommended that a full dive assessment, supervised by an engineer, be conducted to fully capture the structural condition of the floats and mooring piles/chains and anchors. Additionally, any submerged mooring elements were not reviewed, and the structural adequacy of the existing mooring system arrangement is unknown. A mooring study of the configuration and upgrades to the system, if required, are also recommended.

The approach is generally in serviceable condition with minor items noted for repair as follows:

- Clean debris and vegetative growth from the substructure elements
- Replace one cross brace that is deteriorated

The gangway is generally in serviceable condition. The steel elements have large scale coating failures and are significantly corroded. It is recommended that the coating be removed and the steel cleaned and brushed down to competent metal. Once cleaned, it is recommended that an engineering review of the steel elements to confirm structural adequacy. If acceptable the steel is to be re-coated to extend the design life. Additional remedial items are as follows:

- Replace one deck board
- Replace one kick plate and install a second kick plate that is missing
- Install transition plate on seaward end
- Clean and coat angle guides on float deck.

The main public floats (Float A-D) and their associated slips are in overall serviceable condition. Minor remedial recommendations are as follows:

- Replace six bull rails in kind,
- Replace one rub board in kind
- Install appropriate float to float connection brackets on Float A
- Replace damaged cleat on slip D-3.

Float H is in overall serviceable condition. The mooring hoop is significantly corroded and requires cleaning and re-coating.

The Fire Department Walkway Floats Float (E, F, G and associated slips) are no longer in

serviceable condition. The timber superstructure is significantly deteriorated, and the floatation is inconsistent and damaged. The floats list significantly under minor loading and are at the end of their service life. Replacement of the floats is recommended.

The repairs noted in this report are to Class D standard, in 2025 Canadian dollars. For the immediate repairs, the estimated total cost, rounded to the nearest thousand dollars, is \$298,000.00. Demolition of the existing infrastructure and full replacement in kind is estimated as \$2,433,000.00. Refer to Section 6 for detailed cost estimates.

Table of Contents

| | |
|--|----|
| 1.0 INTRODUCTION | 7 |
| 1.1 Purpose of Assignment..... | 7 |
| 1.2 Scope of Work | 7 |
| 1.3 Reference Material..... | 8 |
| 1.4 Methodology | 8 |
| 1.5 Reference System..... | 9 |
| 1.6 Rating Scale and Risk Rating | 9 |
| 2.0 DESCRIPTION AND GEOMETRY | 11 |
| 2.1 Approach | 11 |
| 2.2 Gangway..... | 11 |
| 2.3 Floats..... | 11 |
| 2.3.1 Float A | 12 |
| 2.3.2 Float B..... | 12 |
| 2.3.3 Float C | 13 |
| 2.3.4 Float D | 13 |
| 2.3.5 Float H..... | 13 |
| 2.3.6 Fire Department Floats (Floats E, F, G and Slips F-1 and F-2)..... | 13 |
| 3.0 ASSESSMENT RESULTS..... | 14 |
| 3.1 Approach | 14 |
| 3.2 Gangway..... | 14 |
| 3.3 Floats..... | 15 |
| 3.3.1 Float A | 15 |
| 3.3.2 Float B..... | 16 |
| 3.3.3 Float C | 16 |
| 3.3.4 Float D | 17 |
| 3.3.5 Float H..... | 17 |
| 3.3.6 Fire Department Floats (Floats E, F, G and Slips F-1 and F-2)..... | 18 |
| 4.0 RECOMMENDATIONS..... | 18 |
| 4.1 Approach | 18 |
| 4.2 Gangway..... | 18 |
| 4.3 Floats..... | 19 |
| 4.3.1 Float A | 19 |
| 4.3.2 Float B..... | 19 |

| | |
|--|----|
| 4.3.3 Float C | 19 |
| 4.3.4 Float D | 19 |
| 4.3.5 Float H..... | 20 |
| 4.3.6 Fire Department Floats (Floats E, F, G and Slips F-1 and F-2)..... | 20 |
| 5.0 RESIDUAL LIFE ESTIMATES..... | 20 |
| 5.1 Approach | 20 |
| 5.2 Gangway..... | 20 |
| 5.3 Float A | 20 |
| 5.4 Float B..... | 21 |
| 5.5 Float C | 21 |
| 5.6 Float D | 21 |
| 5.7 Float H..... | 21 |
| 5.8 Fire Department Floats (Floats E, F, G and Slips F-1 and F-2)..... | 21 |
| 6.0 COST ESTIMATES..... | 21 |

1.0 INTRODUCTION

Location: Grappler St. Wharf, Bamfield, BC

Assessment by: Shannon Summersides, P. Eng. (Herold Engineering Ltd.)
Blair Forsyth (Herold Engineering Ltd.)

Date: January 27, 2025

1.1 Purpose of Assignment

The assessment was conducted to identify members either requiring repairs or showing signs of deterioration. The assessment results, detailed in the following report, will provide information regarding maintenance, repair, replacement and health and safety on a ten-year forecasted period, allowing for a prioritized repair and maintenance program to be implemented. Other items noticed during the assessment will be reported only in terms of general overall condition.

All repair/replacement recommendations will be accompanied by a Class D cost estimate, as well as a Class D level estimate of costs associated with complete structure replacement. These estimates are intended to inform maintenance and upgrade budgeting for the ACRD.

Where applicable, recommendations will be made for additional structural assessment in the form of seismic review and/or structural load rating. These recommendations are intended to inform budgeting strategies for future work as required.

1.2 Scope of Work

Herold Engineering travelled to Bamfield to review the Grappler St. wharf on January 27, 2025. The infrastructure was reviewed from above water only.

The assessment included detailed above water visual / tactile inspection of the following components:

- § Abutment
- § Handrails
- § Vehicle Guard
- § Deck Planks
- § Stringers
- § Pile Caps
- § Cross Bracing
- § Wale Timbers
- § Piles

Items assessed specific to floats:

- § Gangways and Connections
- § Bull Rails and Risers
- § Rub Boards
- § Deck Boards
- § Deck Accessories (mooring cleats, signage, lighting, etc)
- § Floatation (where visible)
- § Mooring System (anchor chains) (where visible)

§ Mooring System (mooring piles)

Herold Engineering generated and populated a structural checklist for the structure(s) which includes:

- General dimensions (length and width),
- Structural component sizes and lengths,
- Assessment of the existing condition of the elements based on an owner approved rating scale.

Herold Engineering generated the following report which includes:

- Remediation recommendations,
- Risk analysis,
- Residual life estimates
- Class D cost estimate of the repair recommendations
- Class D cost estimate for full replacement of the structure
- General comments on suitability for seismic loads and load rating

1.3 Reference Material

- Procedures for Inspection and Assessment of Fixed Timber Docks – 1994 September – 4th Edition by R.G. Sexsmith Ltd.
- Canadian Highway Bridge Design Code CAN/CSA S6-19.
- ACRD Risk Management Policy
- ACRD Risk Framework Matrix

1.4 Methodology

The infrastructure was reviewed by Herold Engineering Limited (Herold Engineering) from above water only. The assessment included detailed visual and tactile assessment of accessible elements.

The condition assessment and residual life estimates were based on previous experience, as well as the reference material noted in Section 1.3. Although these assessments can verify much of the visible and tactile damage, they are somewhat limited in assessing the severity and extent of internal damage to timber elements, especially damage due to decay and/or borer insect damage.

All recommendations related to health and safety are provided based upon our experience with structures similar in form and function.

Comments on seismic aspects of the structure are in general terms only. Should Herold Engineering locate structure(s) with higher seismic risk a detailed desktop analysis of the structure seismic response will be recommended.

Load rating analysis is considered outside the scope of the assessments; however, structures considered light duty for the intended use will be recommended for future load rating desktop study.

Class D cost estimates are based on current industry construction rates for mobilization, demobilization, and material costs for supply and installation, as well as historical data from similar projects. All costs are high level and considered appropriate for budget projections only.

Construction costs can be challenging to estimate in the current economic climate, and it is to be noted that prices may change often and can differ significantly based on many fluctuating variables (material costs, mobilization costs, etc). Should the ACRD postpone work for more than six months, it is recommended an updated estimate be generated to reflect current construction costs.

A risk analysis was conducted for the infrastructure, using a modified version of the Alberni-Clayoquot Regional District (ACRD) risk framework (provided to Herold Engineering). The risk framework has been generated to evaluate the level of risk of noted deterioration/damage allowing for prioritization of future repairs and their implications on structure use and life safety. All documents were provided by The ACRD and are referenced in Section 1.3 above.

The following appendices can be found at the end of this report:

- APPENDIX A - Site Photographs
- APPENDIX B - Damage Table
- APPENDIX C - Condition Assessment Checklists
- APPENDIX D - Aerial Map

1.5 Reference System

Grappler St. Wharf is accessed from Grappler Street, located on the eastern side of Bamfield. The marine infrastructure is utilized by the public and the local fire department. The infrastructure is currently maintained by the local Parks Department, Fire Department, and Alberni-Clayoquot Regional District (ACRD) as a collaborative effort.

The approach and gangway generally run north to south, while the floating dock structures run both east to west and north to south. Refer to the following figure for an aerial view of the structure(s).



Figure 1: Aerial Photograph of the Marine Infrastructure

1.6 Rating Scale and Risk Rating

The following is an explanation of the assessment rating scale used in Sections 2 through 5 as it relates to the estimated time before the next required repair to a specific item.

- Very Good (VG) - Element is in serviceable condition with no notable deterioration. No

- Good (G) - repairs are required.
- Element has minor amounts of superficial deterioration with no noted overstressing or structural damage.
- Fair (F) - Element has moderate amounts of damage which may increase rates of deterioration long term. No noted overstressing is observed. Repairs to prolong service life may be applicable.
- Poor (P) - Element has significant amounts of damage or deterioration. No overstressing is observed. The element is nearing the end of its service life.
- Very Poor (VP) - Element is no longer in serviceable condition with significant amounts of damage or loss of structural capacity. Immediate repair or replacement is likely required.

For timber elements exposed to moisture such as the deck boards on the bridge, the assessment rating scale corresponds to an estimated remaining service life as follows:

- Very Good (VG) - 10 years
- Good (G) - 6 to 10 years
- Fair (F) - 3 to 6 years.
- Poor (P) - 1 to 3 years
- Very Poor (VP) - 0 years

The assessment rating scale correlates to the risk rating based on the structural consequences associated with element deterioration and/or failure. The consequence rating scale is as follows:

- Negligible (N) - Element failure has no effect on structural capacity, nor usage/performance (e.g.: coating failures)
- Minor (M) - Element failure results in no effect on structural capacity and has a minor effect on usage/performance (e.g.: damage to guarding, signage etc.)
- Moderate (Mod) - Element failure leads to local failure only. This can impact usage (e.g.: settlement of abutments, listing of the structure, loose decking)
- Significant (S) - Element failure probably does not lead to total collapse due to continuity and/or multiple load paths. Other main structural members in the system may become overloaded due to the failure. This includes main load carrying members (e.g.: girder in a multi-girder system)
- Collapse (C) - Element failure leads to total collapse of the structure. This includes failure of main members with no benefit from continuity or multiple-load paths (e.g.: simply supported girder in a two-girder system)

The assessment and consequence rating scales are combined to create a risk rating matrix as follows:

| | | Assessment Rating | | | | |
|--------------------|-----|-------------------|----|----|----|----|
| | | VG | G | F | P | VP |
| Consequence Rating | N | 1 | 2 | 3 | 4 | 5 |
| | M | 2 | 4 | 6 | 8 | 10 |
| | Mod | 3 | 6 | 9 | 12 | 15 |
| | S | 4 | 8 | 12 | 16 | 20 |
| | C | 5 | 10 | 15 | 20 | 25 |

Refer to Appendix B for damage table risk rating for individual items.

2.0 DESCRIPTION AND GEOMETRY

The marine infrastructure is generally composed of an approach trestle, gangway and various floating structures including walkway floats, slips and a boathouse float.

2.1 Approach

The approach is a fixed treated timber structure. The superstructure is comprised of treated timber guarding (handrails and vehicle guards), deck boards, and stringers. The superstructure is supported by a substructure of treated timber pile caps and bearing piles. Intermittent cross bracing spans the bearing piles providing lateral support.

The component sizes are as follows:

| | | |
|---------------|---|------------------------------------|
| Handrails | - | 102mm x 102mm (posts) |
| | - | 38mm x 140mm (top and bottom rail) |
| | - | 38mm x 89mm (mid rail) |
| Vehicle Guard | - | 102mm x 152mm |
| Deck Boards | - | 52mm x 152mm |
| Stringers | - | 89mm x 242mm |
| Pile Caps | - | 305mm x 242mm |
| Bearing Piles | - | 305mm diameter (size 36) |
| Cross Braces | - | 89mm x 140mm and 140mm x 191mm |

2.2 Gangway

The gangway is a coated steel truss structure, typical for legacy facilities of this nature. The truss is comprised of top and bottom chords, vertical members, and diagonal members. The gangway is supported by drop hinges on the approach structure. The gangway lands on the float (Float A) and articulates with the float through the tidal range via a steel roller assembly. There is a landing pad and guide angles mounted to the float to guide the roller and protect the float deck where the gangway touches down.

The gangway has treated timber decking and a kick plate on one side of the handrail.

The component sizes are as follows:

| | | |
|--------------|---|-----------------------------|
| Top Chord | - | L89mm x 64mm steel angle |
| Bottom Chord | - | C76 steel channel |
| Verticals | - | L25x25 steel angle |
| Diagonals | - | L25x25 steel angle |
| Deck Boards | - | 38mm x 292mm treated timber |
| Kick Plate | - | 38mm x 140mm treated timber |

2.3 Floats

The floating docks are all a similar construction.

The superstructure is typically timber bull rails and decking, which are supported by a substructure of timber joists and flanges. The floats are buoyed by mixed floatation types including encased billet floatation, raw polystyrene billet floatation, foam filled tires, and/or log floatation.

Refer to the following aerial sketch for float designations and arrangement.




Figure 2: Aerial Sketch of Float Arrangement

2.3.1 Float A

Float A is a treated timber construction with two distinct floating sections. One section is an older float located at the seaward end and the other section is a newer construction located on the shoreward end. There is a compact mooring dolphin at the junction between the two float sections, comprised of four mooring piles in an internal mooring well. There is a spread mooring dolphin at the shoreward end comprised of two groups of two piles.

The component sizes are as follows:

- Deck Boards - 38mm x 292mm
- Rub Board - 38mm x 292mm (shoreward)/ 51x254/150mm (seaward)
- Bull Rail - 89mm x 140mm (shoreward)/ 102mm x 102mm (seaward)

- Floatation - log floatation
- tire floatation
- Mooring Piles - 305mm diameter (size 36)

2.3.2 Float B

Float B is a treated timber construction similar to Float A. There is an older float section at the seaward end of the float and a newer section at the shoreward end. There is a single mooring pile at the northeast corner of the float.

The component sizes are as follows:

- Deck Boards - 38mm x 190mm (new)/ 38mm x 140mm (old)
- Rub Board - 38mm x 241mm (new)/ 38mm x 292mm (old)
- Bull Rail - 102mm x 152mm (new)/ 89mm x 140mm (old)

| | | |
|---------------|---|--|
| Floatation | - | 1.52m x 1.22m encased billet floatation (only type verified) |
| Mooring Piles | - | 305mm diameter (size 36) |

2.3.3 Float C

Float C is a treated timber construction with five float slips extending west from along the float length. The slips are outfitted with mooring cleats and are of similar construction to the adjacent floats. There is a compact mooring dolphin on the east edge of the float, approximately in line with slip C-3. The dolphin is comprised of two mooring piles.

The component sizes are as follows:

| | | |
|---------------|---|--|
| Deck Boards | - | 38mm x 190mm |
| Rub Board | - | 38mm x 241mm |
| Bull Rail | - | 102mm x 152mm |
| Joists | - | 102mm x 102mm |
| Floatation | - | 1.52m x 1.22m encased billet floatation (only type verified) |
| Mooring Piles | - | 305mm diameter (size 36) |

2.3.4 Float D

Float D is similar in construction to Float C. It is a treated timber construction with a compact mooring dolphin located on the southern edge approximately aligned with Float C. The mooring dolphin is comprised of three mooring piles. There are three slips extending from the south edge of Float D.

The component sizes are as follows:

| | | |
|---------------|---|--------------------------|
| Deck Boards | - | 38mm x 190mm |
| Rub Board | - | 38mm x 241mm |
| Bull Rail | - | 102mm x 152mm |
| Mooring Piles | - | 305mm diameter (size 36) |

2.3.5 Float H

Float H is a treated timber construction with a conventional single storey wood-framed structure mounted on the float deck. The float is u-shaped to accommodate a vessel within the house.

The component sizes are as follows:

| | | |
|-------------|---|-----------------------------------|
| Deck Boards | - | 52mm x 152mm |
| Rub Board | - | 52mm x 305mm |
| Stringers | - | 127mm x 305mm at 1.219m on center |
| Floatation | - | encased billet floatation |

2.3.6 Fire Department Floats (Floats E, F, G and Slips F-1 and F-2)

The fire department floats include Floats E, F, G and slips F-1 and F-2. The floats and slips are a mixed timber construction. It is understood that the floats have been relocated and used to be the only floating infrastructure. During a major upgrade, new floats and slips were

installed and the older floats were repurposed for this location. The member sizing and floatation types are varied throughout the floats.

The floats are secured to the walkway float and Float C via ropes. It is understood that some chain and anchor systems moor the floats, but this was not verifiable during the assessment.

The component sizes are as follows:

| | | |
|-------------|---|--------------------------------------|
| Deck Boards | - | (mixed) 38mm x 292mm |
| Rub Board | - | (mixed) 38mm x 241mm |
| Bull Rail | - | (mixed) 89mm x 89mm |
| Floatation | - | (mixed) exposed polystyrene observed |

3.0 ASSESSMENT RESULTS

The following section summarizes the results of the findings on-site. Refer to Appendix B for a detailed breakdown of element damage type, severity and location.

3.1 Approach

The approach is in serviceable condition. There is moderate weathering and biological growth to the superstructure and substructure, which is typical of structures of this form and function.

The following items were noted while on-site:

- Approach stringers and pile caps have biological growth along surfaces, wood section is competent when probed.
- Pile caps generally have bolts penetrating their section, with notable checking on the underside of the elements. This compromises the treatment layer. Pile caps are competent when probed.
- One cross brace cut end is decayed with visible deterioration of the cross section.

3.2 Gangway

The gangway is in overall serviceable condition. There are localized, but widespread, coating failures on the steel elements. These locations have significant surface corrosion and are beginning to delaminate. Without intervention, the gangway is nearing the end of its service life.

The following items were noted while on-site:

- One deck board is decayed and missing a portion of the cross section at the connection point.
- Kick plate is decayed at cut end.
- Kick plate is missing on the west side of gangway
- Drop hinges and steel truss elements have notable coating failures and surface corrosion.

- Cross beams of steel truss are beginning to delaminate with corrosion penetrating the surface of the members.
- The seaward transition plate is missing, which is a possible tripping hazard.
- Angle guides on landing pad are visibly corroded with delamination of the steel.

3.3 Floats

The new floats (Float A, B, C and D) and associated slips are in overall fair to poor serviceable condition.

The older floats utilized by the fire department (Float E, F, G and associated slips) are in very poor condition and are at the end of their service life. See Section 3.3.5 and Appendix B for details.

Float H is in overall good serviceable condition.

Generally, all the floats have a mix of mooring types. A mooring study of the floats is recommended to ensure the infrastructure is appropriately anchored within the marina basin.

All floats were reviewed from above water. A detailed dive assessment is recommended, in conjunction with the mooring study, to confirm the condition of submerged elements are the site. This would include float substructure, floatation, mooring piles and mooring chain and anchor.

3.3.1 Float A

Float A is in overall poor serviceable condition. The following items were noted while on-site:

- Deck boards below the gangway and in select locations along the float length are decayed with loss of cross section in some areas.
- There are two bull rails which are missing on the float, as well as two sections of rail that are significantly decayed.
- One section of rub board has failed on the float.
- The float-to-float connection at the junction between the old and new sections is secured with chain to the existing bull rails. This connection is not typical, and the bull rails are in poor condition.
- Visible areas of the substructure are decayed with vegetative growth present where accessible.
- Floatation is a mix of log and foam filled tire floatation. The float is somewhat listing.

Float freeboard measurements were taken around the perimeter and are as follows:

| <i>Location</i> | <i>Measurement (mm)</i> |
|------------------|-------------------------|
| Northwest Corner | 381 |
| Northeast Corner | 406 |
| Mid-float West | 387 |
| Mid-float East | 406 |
| Southwest Corner | 431 |

| <i>Location</i> | <i>Measurement (mm)</i> |
|-------------------------|-------------------------|
| <i>Southeast Corner</i> | 330 |

The float freeboards are within acceptable tolerances except for the southeast corner. It is evident that the timber elements have taken on water and that floatation may be missing at this location.

3.3.2 Float B

Float B is in overall fair serviceable condition. The following items were noted while on-site:

- One deck board is loose and not secured to the substructure.
- One riser is missing.
- One bull rail and one riser are decayed with visible deterioration of the cross section.
- There is a check in the mooring pile which penetrates the creosote layer.

Float freeboard measurements were taken around the perimeter and are as follows:

| <i>Location</i> | <i>Measurement (mm)</i> |
|-------------------------|-------------------------|
| <i>Northwest Corner</i> | 292 |
| <i>Northeast Corner</i> | 228 |
| <i>Mid-float West</i> | 362 |
| <i>Mid-float East</i> | 330 |
| <i>Southwest Corner</i> | 457 |
| <i>Southeast Corner</i> | 438 |

The float freeboards are no longer within acceptable tolerances. The north end of the float is listing significantly, likely due to the older age of the section and anticipated increases in floatation deterioration and substructure aging.

3.3.3 Float C

Float C and associated slips are in overall fair to poor serviceable condition. The following items were noted while on-site:

- The bull rail is missing at the end of the float.
- Moderate mechanical damage due to abrasion on the mooring piles.

Float freeboard measurements were taken around the perimeter and are as follows:

| <i>Location</i> | <i>Measurement (mm)</i> |
|-------------------------|-------------------------|
| <i>Northwest Corner</i> | 432 |
| <i>Northeast Corner</i> | 419 |
| <i>Mid-float East</i> | 387 |
| <i>Southwest Corner</i> | 438 |
| <i>Southeast Corner</i> | 482 |
| <i>Slip C-5</i> | 381 |
| <i>Slip C-4</i> | 368 |
| <i>Slip C-3</i> | 362 |
| <i>Slip C-2</i> | 381 |

| <i>Location</i> | <i>Measurement (mm)</i> |
|-----------------|-------------------------|
| <i>Slip C-1</i> | 356 |

The float freeboards are within acceptable tolerance and there are no concerns with the floatation performance.

3.3.4 Float D

The Float D and associated slips are in overall good to fair serviceable condition. The following items were noted while on-site:

- Moderate mechanical damage due to abrasion on the mooring piles.
- One cleat on Slip D-3 has sheared off.

Float freeboard measurements were taken around the perimeter and are as follows:

| <i>Location</i> | <i>Measurement (mm)</i> |
|-------------------------|-------------------------|
| <i>Northwest Corner</i> | 406 |
| <i>Northeast Corner</i> | 445 |
| <i>Mid-float North</i> | 457 |
| <i>Mid-float South</i> | 445 |
| <i>Southwest Corner</i> | 425 |
| <i>Southeast Corner</i> | 445 |
| <i>Slip D-3</i> | 508 |
| <i>Slip D-2</i> | 508 |
| <i>Slip D-1</i> | 533 |

The float freeboards are within acceptable tolerance and there are no concerns with the floatation performance.

3.3.5 Float H

The Float H is in overall good serviceable condition. The structure appears to be in good condition and the float is relatively new.

The following items were noted on-site:

- Deck board fasteners do not consistently have sufficient edge distance to the cut end of the deck board elements. Some boards have cracked through the hardware locations.
- Deck board fasteners are loose in localized areas.
- Mooring pile hoop and bracket are significantly corroded.

Float freeboard measurements were taken around the perimeter and are as follows:

| <i>Location</i> | <i>Measurement (mm)</i> |
|-------------------------|-------------------------|
| <i>Northwest Corner</i> | 560 |
| <i>Northeast Corner</i> | 560 |
| <i>Southwest Corner</i> | 560 |

Southeast Corner

560

The float freeboards are within acceptable tolerance and there are no concerns with the floatation performance.

3.3.6 Fire Department Floats (Floats E, F, G and Slips F-1 and F-2)

The fire department floats are at the end of their service life and are in overall poor to very poor condition. The superstructure is significantly weathered with areas of cross section loss and decay. Deck boards and bull rails are missing in select areas.

The substructure has evidence of biological decay and water ingress, with floats listing significantly. Floatation is missing, has failed, and/or has taken on water in several locations. Float freeboards are inconsistent, and float stability is unpredictable in several locations.

The float-to-float connections are not typical, several floats are secured with rope to adjacent floats using bull rails and/or cleats. These connections are not considered structurally reliable.

Float freeboard measurements were taken around the perimeter of the floats and average 275mm, with freeboards as low as 127mm. This is well below a typical design freeboard for floats of this form and function. Some floats are missing floatation and list significantly when loaded. This is indicative of failures/damage to the substructure and floatation and is typical of floats nearing the end of their service life.

4.0 RECOMMENDATIONS

4.1 Approach

The following remedial activities are recommended within the next year:

- Cleaning of the stringers and pile caps to remove vegetative growth,
- Ongoing monitoring of the pile cap sections damage by thru-bolts,
- Replace one cross brace.

4.2 Gangway

The following remedial activities are recommended within the next year:

- Replace one deck board,
- Replace one kick plate and install a second kick plate,
- Clean drop hinges and steel elements of all delaminated, corroded steel and have the elements reviewed by an engineer registered to practice in British Columbia to ensure the remaining section is sufficient.
- Recoat cleaned steel elements or replace steel truss elements where appropriate,
- Install a transition plate at seaward transition to Float A,
- Clean corrosion off angle guides and evaluate remaining thickness. Replace or re-

coat guides as appropriate.

4.3 Floats

Generally, it is recommended that a dive assessment be conducted to determine the existing condition of the submerged float elements, as well as to complete a mooring study of the float arrangement and ensure the structures are adequately moored.

4.3.1 Float A

The following remedial activities are recommended within the next year:

- Replace five deck boards in kind,
- Install two missing bull rails,
- Replace two decayed bull rails in kind,
- Replace rub board in kind,
- Replace float-to-float connections with engineered chain and mounting bracket connections,
- Ongoing monitoring of floatation via freeboard measurement.

4.3.2 Float B

The following remedial activities are recommended within the next year:

- Re-secure deck boards to substructure,
- Replace one bull rail in kind,
- Install one riser to match existing,
- Replace one riser in kind,
- Ongoing monitoring of damage to mooring pile creosote layer.

4.3.3 Float C

The following remedial activities are recommended within the next year:

- Install bull rail to match existing,
- Ongoing monitoring of damage to mooring pile creosote layer.

4.3.4 Float D

The following remedial activities are recommended within the next year:

- Replace one cleat on slip D-3.

4.3.5 Float H

The following remedial activities are recommended within the next year:

- Secure loose hardware on deck,
- Ongoing monitoring of deck boards, replace as elements fail through connection points,
- Ongoing monitoring of the mooring hoop, consider cleaning and re-coating during remediation of the gangway steel.

4.3.6 Fire Department Floats (Floats E, F, G and Slips F-1 and F-2)

The floats and slips are at the end of their service life. Most of the structural elements require replacement, and most of the floats need all new floatation. It is likely more cost effective to replace the floats in kind or with a floating configuration that is better suited to the service requirements of the fire department.

5.0 RESIDUAL LIFE ESTIMATES

The residual life estimates are based on the rating scale defined in Section 1.6 above. These estimates represent the worst-case members inspected in any member group. For this reason, the overall condition of the member group is not necessarily reflected by the following residual life estimates.

See Appendix B to determine which members the residual life estimate applies to.

5.1 Approach

| | |
|---------------|--|
| Handrails | 6-10 years based on overall condition |
| Vehicle Guard | 6-10 years based on overall condition |
| Deck Boards | 3-6 years based on overall condition and exposure |
| Stringers | 3-6 years based on overall condition and exposure |
| Pile Caps | 3-6 years based on one pile cap with damage |
| Bearing Piles | 6-10 years based on overall condition and exposure |
| Cross Bracing | 1-3 years based on one cross brace to be replaced |

5.2 Gangway

| | |
|-------------|---|
| Kick Plate | 0-1 year based on missing and deteriorated elements |
| Deck Boards | 0-1 year based on one board requiring replacement |

5.3 Float A

| | |
|-------------|---|
| Bull Rails | 0 years based on two bull rails requiring replacement |
| Deck Boards | 0 years based on several boards requiring replacement |

| | |
|----------------|--|
| Rub Boards | 0 years based on one rub board requiring replacement |
| Mooring Piles* | 3-6 years based on overall condition and exposure |

5.4 Float B

| | |
|----------------|---|
| Bull Rails | 0 years based on one bull rail condition |
| Deck Boards | 1-3 years based on one loose deck board |
| Rub Boards | 3-6 years based on overall condition and exposure |
| Mooring Piles* | 3-6 years based on overall condition and exposure |

5.5 Float C

| | |
|----------------|---|
| Bull Rails | 0 years based on one missing bull rail |
| Deck Boards | 3-6 years based on overall condition and exposure |
| Rub Boards | 3-6 years based on overall condition and exposure |
| Mooring Piles* | 3-6 years based on overall condition and exposure |

5.6 Float D

| | |
|----------------|---|
| Bull Rails | 6-10 years based on overall condition |
| Deck Boards | 3-6 years based on overall condition and exposure |
| Rub Boards | 3-6 years based on overall condition and exposure |
| Mooring Piles* | 3-6 years based on overall condition and exposure |

5.7 Float H

| | |
|----------------|--|
| Deck Boards | 6-10 years based on overall condition and exposure |
| Rub Boards | 6-10 years based on overall condition and exposure |
| Mooring Piles* | 3-6 years based on overall condition and exposure |

5.8 Fire Department Floats (Floats E, F, G and Slips F-1 and F-2)

| | |
|--------------|--------------------------------------|
| Bull Rails | 0-1 years based on overall condition |
| Deck Boards | 0-1 years based on overall condition |
| Rub Boards | 0-1 years based on overall condition |
| Substructure | 0-1 years based on overall condition |

* Note: mooring piles were only observed from above water. The residual life estimate may not be accurate if the submerged condition was known. A dive assessment is recommended within the next year.

6.0 COST ESTIMATES

The repairs noted in this report are estimated to Class D standard, in 2025 Canadian dollars. They are based on historical data, current industry rates, as well as our experience with projects of this nature.

The following cost estimate assumes that a construction crew has mobilized one time to

repair/replace all four bridges. It is to be noted that construction costs fluctuate significantly in the current economic climate. It is recommended that if repairs are delayed more than six months, a revised estimate be generated. Additionally, should detailed design of replacement structures occur, costing should be redone to ensure accuracy for budgeting and maintenance projections.

It is to be noted that the submerged elements of the assets were not reviewed as part of the scope of work. A detailed dive assessment is recommended and included in the estimate below (Table 6.1). Additionally, the float moorage configuration and adequacy are unknown. A mooring study is recommended and included in the estimate below.

Neither estimate (Table 6.1 nor 6.2) accounts for additional float moorage that may be present other than the mooring piles observed on-site. This includes any existing chain and anchor or alternate moorage not visible at the time of the assessment.

Table 6.1 Cost Estimate for Recommended Repairs

| ITEM | LOCATION | RECOMMENDATION | COST (\$) |
|---------------------------------|----------------------|---|-------------|
| Mobilization/Demobilization | | | \$25,000.00 |
| Underwater Assessment of Assets | | | \$15,000.00 |
| Float Mooring Study | | | \$5,000.00 |
| Approach | | | |
| Stringers/ Pile Caps | General | Clean substructure | \$500.00 |
| Cross Brace | Bent 2 | Ongoing monitoring. Replace cross brace within the next three years. | \$1,000.00 |
| Gangway | | | |
| Deck Board | Southeast corner | Replace deck board | \$170.00 |
| Kick Plate | East side | Replace first section of kick plate | \$850.00 |
| Kick Plate | West side | Provide kick plate on west side | \$850.00 |
| Drop Hinges | South End | Clean off surface corrosion and re-coat hinges and associated hardware | \$2,000.00 |
| Struss Elements | General | Clean off surface corrosion and scaling. Have an engineer evaluate the remaining condition. If acceptable, re-coat gangway steel elements and associated hardware | \$10,000.00 |
| Seaward Transition | At Float | Provide transition plate. | \$2,500.00 |
| Angle Guides | At Float | Clean angle guides. Coat the guides to prolong life. If the remaining thickness is less than 6mm, replace angle guides in kind. | \$1,750.00 |
| Float A | | | |
| Deck Boards | Under gangway at 0m | Replace affected deck boards in kind. | \$1,300.00 |
| Deck Board | At 35.3m | Replace the deck board in kind. | \$275.00 |
| Bull Rail | At 0m on west edge | Install bull rail to match existing. | \$950.00 |
| Bull Rail | At 7.0m on east edge | Replace two affected lengths of bull rail. | \$1,900.00 |
| Bull Rail | At 28m on west edge | Install bull rail to match existing. | \$950.00 |
| Rub Board | At 11m on west edge | Replace the rub board in kind. | \$350.00 |

| ITEM | LOCATION | RECOMMENDATION | COST (\$) |
|---|--|--|--------------|
| Connection | Mid float between sections (east and west) | Replace connections with engineered chain connections with mounting plates or equivalent. | \$5,000.00 |
| Float B | | | |
| Deck Boards | at 0m | Re-secure deck boards to the substructure | \$50.00 |
| Bull Rail | At 12.2m on east side | Install riser to match existing. | \$50.00 |
| Bull Rail | At 23.1m on west side | Replace affected bull rail in kind. | \$950.00 |
| Bull Rail | At 32.9m on west side | Replace riser in kind. | \$50.00 |
| Float C | | | |
| Bull Rail | North end | Install bull rail to match existing. | \$375.00 |
| Float D | | | |
| Cleat | D-3 | Replace damaged cleat | \$500.00 |
| Float H | | | |
| Mooring Pile Hoop | General | Clean surface rust and re-coat hoop | \$1,000.00 |
| Fire Department Floats (Floats E, F, G and Slips F-1 and F-2) | | | |
| Deck Boards | General | Float is at or nearing the end of its service life. Replacement of float structures in their entirety is recommended. It is also recommended that new moorage be explored that is sufficient for the loading and exposure. | \$170,000.00 |
| Bull Rails | General | | |
| Rub Boards | General | | |
| Substructure | General | | |
| Floatation | General | | |
| Connections | General | | |

| | |
|-------------------|---------------------|
| Subtotal (\$) | \$248,320.00 |
| Contingency (20%) | \$49,664.00 |
| TOTAL (\$) | \$297,984.00 |

Table 6.2 Cost Estimate for Full Replacement
 (NOTE: l.s. = lump sum, l.m. = lineal meter, m² = square meter)

| ITEM | SIZE | UNITS | QUANTITY | UNIT RATE | COST (\$) |
|-----------------------------|---------------|-------|----------|--------------|--------------|
| Mobilization/Demobilization | | l.s. | 1 | \$500,000.00 | \$500,000.00 |
| Demolition | | l.s. | 1 | \$295,000.00 | \$295,000.00 |
| Approach | | | | | |
| Handrails | varies | l.m. | 58 | \$750.00 | \$43,500.00 |
| Vehicle Guard | varies | l.m. | 58 | \$200.00 | \$11,600.00 |
| Deck Boards | 52mm x 152mm | l.m. | 350 | \$175.00 | \$61,250.00 |
| Stringers | 89mmx241mm | l.m. | 116 | \$250.00 | \$29,000.00 |
| Pile Caps | 305mm x 241mm | l.m. | 16 | \$300.00 | \$4,800.00 |

| ITEM | SIZE | UNITS | QUANTITY | UNIT RATE | COST (\$) |
|--|-----------------------------------|----------------|----------|-------------|--------------|
| Bearing Piles | 305mm diameter | each | 16 | \$8,000.00 | \$128,000.00 |
| Cross Bracing | 140mm x 190mm | l.m. | 48 | \$250.00 | \$12,000.00 |
| Gangway | | | | | |
| Steel Truss Gangway, Roller and Drop Hinges | 11m long x 1.372m wide | l.s. | 1 | \$65,000.00 | \$65,000.00 |
| Deck Boards | 38mm x 292mm | l.m. | 55 | \$125.00 | \$6,875.00 |
| Drop Hinges | N/A | l.s. | 1 | \$2,500.00 | \$2,500.00 |
| Transition Plates | N/A | each | 2 | \$3,000.00 | \$6,000.00 |
| Landing Pad and Guide Angles | | l.s. | 1 | \$4,500.00 | \$4,500.00 |
| Float A | | | | | |
| Timber Float | 2.8m x 38.6m | m ² | 108.1 | \$1,375.00 | \$148,637.50 |
| Timber Mooring Pile | 305mm diameter | each | 8 | \$7,000.00 | \$56,000.00 |
| Float B | | | | | |
| Timber Float | 2.13m x 36m | m ² | 76.7 | \$1,375.00 | \$105,462.50 |
| Timber Mooring Pile | 305mm diameter | each | 1 | \$7,000.00 | \$7,000.00 |
| Float C | | | | | |
| Timber Float | 1.83m x 30.6m | m ² | 56 | \$1,375.00 | \$77,000.00 |
| Timber Mooring Pile | 305mm diameter | each | 2 | \$7,000.00 | \$14,000.00 |
| Timber Float Slips | (5)- 1.22m x 4.93m | m ² | 30 | \$1,375.00 | \$41,250.00 |
| Float D | | | | | |
| Timber Float | 1.74m x 22.7m | m ² | 40 | \$2,000.00 | \$80,000.00 |
| Timber Mooring Pile | 305mm diameter | each | 3 | \$7,000.00 | \$21,000.00 |
| Timber Float Slips | (3) - 1.22m x 4.83m | m ² | 17.7 | \$1,375.00 | \$24,337.50 |
| Float H | | | | | |
| Custom Timber Float | 6.1m x 12.2m | m ² | 45.7 | \$1,375.00 | \$62,837.50 |
| Wood-Frame Structure | 6.1m x 12.2m | m ² | 50 | \$2,000.00 | \$100,000.00 |
| Timber Mooring Pile | 305mm diameter | each | 1 | \$7,000.00 | \$7,000.00 |
| Fire Department Floats (Floats E, F, G and Slips F-1 and F-2) | | | | | |
| Timber Float | 1.524m x 33.6m and 1.524m x 20.2m | m ² | 82 | \$1,375.00 | \$112,750.00 |

Subtotal (\$) \$2,202,300.00
 Contingency (20%) \$405,460.00
TOTAL (\$) \$2,432,760.00

Appendix A

Site Photographs



Photograph 1: Grappler St. Wharf, note: general arrangement looking northwest



Photograph 2: Approach, note: general arrangement looking north



Photograph 3: Approach, note: general arrangement looking west



Photograph 4: Approach stringers and pile cap, note: biological growth on surfaces of elements



Photograph 5: Pile Cap at Bent 2, note: check in underside where stringer hardware penetrates section. Loss of treatment layer




Photograph 6: Cross Brace at Bent 2, note: decay at cut end



Photograph 7: Gangway, note: general arrangement looking east



Photograph 8: Gangway deck board and kick plate, note: mechanical damage



Photograph 7: Gangway drop hinges, note: coating failures and surface rust



Photograph 8: Gangway top chord, note: coating failures and surface rust



Photograph 9: Gangway steel elements, note: coating failures and surface rust



Photograph 10: Gangway cross beams, note: failed coating and significant corrosive damage.



Photograph 11: Gangway roller, note: roller pin significantly corroded and delaminating



Photograph 12: Gangway transition, note: no transition plate to float



Photograph 13: Gangway angle guides, note: scaling and corrosion to steel guides




Photograph 14: Float A, note: general arrangement looking northeast



Photograph 15: Float A deck boards under gangway, note: biological decay



Photograph 16: Float A deck boards under gangway, note: biological decay and cross section failure



Photograph 17: Float A at 0m, note: bull rail missing




Photograph 18: Float A bull rail at 7.0m east side, note: decayed bull rail at connections




Photograph 19: Float A Rub board at 11m, note: failed section



Photograph 20: Float A connection west, note: secured to bull rail



Photograph 21: Float A connection east, note: secured to bull rail



Photograph 22: Float A bull rail at 28m on west side, note: missing



Photograph 23: Float A deck board at 35.3m,
note: failed section through
connection to float



Photograph 24: Float A substructure, note:
decayed substructure elements
with visible biological growth



Photograph 25: Float A, note: mixed floatation
including rubber tires



Photograph 26: Float B, note: general
arrangement looking north



Photograph 27: Float B bull rail, note: missing riser
at 12.2m.



Photograph 28: Float B bull rail note: check in
element at 14.8m



Photograph 29: Float B bull rail at 23.1m, note: decayed through section



Photograph 30: Float B bull rail, note: new section of bull rail is smaller than other sections



Photograph 31: Float B bull rail at 32.9m, note: decayed riser



Photograph 32: Float mooring pile, note: mechanical damage through creosote layer



Photograph 33: Float C, note: general arrangement looking north



Photograph 34: Float C mooring piles, note: abrasion damage to creosote layer



Photograph 35: Float C, note: no guarding at north end of float



Photograph 36: Slips C-1 to C-5, note: general arrangement looking south




Photograph 37: Float H, note: general arrangement looking northwest



Photograph 38: Float H decking, note: check through hardware



Photograph 39: Float H decking, note: loose hardware



Photograph 40: Float H mooring pile, note: coating failures and corrosion to bracket



Photograph 41: Slip F-1, note: exposed Styrofoam flotation and listing superstructure



Photograph 42: Fire Department Float, note: decayed float elements



Photograph 43: Float E, note: insufficient connection to adjacent structures



Photograph 44: Fire Department Floats, note: decayed bull rails and decking



Photograph 45: Fire Department Floats, note: decay and weathering to deck and other structural members



Photograph 46: Fire Department Floats, note: decayed bull rails and decking

Appendix B Damage Table

Table B1 Damage Table

**Note: all locations measured from zero datum at the end closest to the shore access point*

| ITEM | LOCATION | DAMAGE | CONDITION | COMMENTS | RECOMMENDATION | RISK | REMEDIAL YEAR |
|--------------------|------------------|---------------------------|--------------|---|---|------|---------------|
| Approach | | | | | | | |
| Stringers | General | Biological | Fair | Stringers have visible biological growth along surfaces. Competent when probed (where accessible) | Clean substructure | 3 | 2025/2026 |
| Pile Cap | General | Mechanical | Fair | Stringer bolts are driven through the pile cap section and have caused checking to the underside. This has compromised the treatment layer. | Ongoing monitoring. | 3 | - |
| Pile Cap | Bent 1 | Biological | Fair to Poor | Pile cap has visible biological growth along surfaces. Competent when probed. | Clean substructure | 12 | 2025/2026 |
| Cross Brace | Bent 2 | Mechanical/ Biological | Fair to Poor | Cut end is beginning to decay. | Ongoing monitoring. Replace the cross brace within the next three years. | 12 | 2028/2029 |
| Gangway | | | | | | | |
| Deck Board | Southeast corner | Mechanical/ Biological | Poor | Deck board has lost part of the section due to mechanical damage. There is visible decay to the cut end | Replace deck board | 12 | 2025/2026 |
| Kick Plate | East side | Mechanical/ Biological | Poor | Section at cut end is deteriorated with visible decay. | Replace first section of kick plate | 4 | 2025/2026 |
| Kick Plate | West side | Missing | Very Poor | Missing kick plate. | Provide kick plate on west side | 5 | 2025/2026 |
| Drop Hinges | South End | Corrosion | Poor to Fair | Significant coating failures and surface corrosion | Clean off surface corrosion and re-coat hinges and associated hardware | 16 | 2025/2026 |
| Struss Elements | General | Corrosion | Poor | Significant and extensive coating failures and surface corrosion | Clean off surface corrosion and scaling. Re-coat gangway steel elements and associated hardware | 16 | 2025/2026 |
| Seaward Transition | At Float | Missing | Very Poor | No transition plate from gangway to float at seaward end. This is a tripping hazard. | Provide transition plate. | 10 | 2025/2026 |
| Angle Guides | At Float | Corrosion | Poor | Angle guides are visibly corroded with delamination and scaling | Clean angle guides. Coat the guides to prolong life. If the remaining thickness is less than 6mm, replace angle guides in kind. | 10 | 2025/2026 |
| Float A | | | | | | | |

| ITEM | LOCATION | DAMAGE | CONDITION | COMMENTS | RECOMMENDATION | RISK | REMEDIAL YEAR |
|----------------|--|-----------------------|--------------|---|---|------|---------------|
| Deck Boards | Under gangway at 0m | Biological | Very Poor | Deck boards are decaying with vegetative growth that likely affects substructure below | Replace affected deck boards in kind. | 15 | 2025/2026 |
| Deck Board | At 35.3m | Mechanical/Biological | Poor | Section is visibly decayed at the cut end. The section has deteriorated through connection point to float substructure. | Replace the deck board in kind. | 15 | 2025/2026 |
| Bull Rail | At 0m on west edge | Missing | Very Poor | Bull rail is missing. | Install bull rail to match existing. | 15 | 2025/2026 |
| Bull Rail | At 7.0m on east edge | Biological | Poor | Bull rail is decayed through connection to float. Decay penetrates in section | Replace two affected lengths of bull rail. | 12 | 2025/2026 |
| Bull Rail | At 28m on west edge | Missing | Very Poor | Bull rail is missing. | Install bull rail to match existing. | 15 | 2025/2026 |
| Rub Board | At 11m on west edge | Mechanical/Biological | Very Poor | Section has failed and float substructure is exposed. | Replace the rub board in kind. | 10 | 2025/2026 |
| Connection | Mid float between sections (east and west) | - | Fair to Poor | Heavy chain connects two floats. Chain is secured to bull rails. There is visible decay and the connection is uncertain | Replace connections with engineered chain connections with mounting plates or equivalent. | 16 | 2025/2026 |
| Substructure | General | Biological | Fair to Poor | Localized areas of substructure decay with visible vegetative growth and softness when probed. | Conduct detailed dive assessment to confirm the substructure condition. Otherwise, consider for replacement within 3 years. | 16 | 2025/2026 |
| Floatation | General | - | - | Floatation appears to be of mixed construction, indicative of intermittent repair/ piecemeal replacement. | Ongoing monitoring for listing and/or missing floatation | - | - |
| Float B | | | | | | | |
| Deck Boards | at 0m | Mechanical/Biological | Very Poor | One deck board is loose. | Re-secure deck boards to the substructure | 15 | 2025/2026 |
| Bull Rail | At 12.2m on east side | Missing | Very Poor | Bull rail is missing riser at this location. | Install riser to match existing. | 15 | 2025/2026 |
| Bull Rail | At 14.8m on east side | Mechanical | Fair | Moderate check in bull rail length. | Ongoing monitoring. | 9 | - |
| Bull Rail | At 23.1m on west side | Biological | Very Poor | Bull rail section is decayed at the connection with 75% of cross section gone. | Replace affected bull rail in kind. | 15 | 2025/2026 |
| Bull Rail | At 32.9m on west side | Biological | Poor | Riser is significantly decayed. | Replace riser in kind. | 12 | 2025/2026 |
| Bull Rail | General | - | - | Bull rails appear to be replaced in random locations. The newer sections are smaller than the previous elements. | Ongoing monitoring. Moving forward, the best practice would be to have all bull rails of the same sectional dimensions. | - | - |

| ITEM | LOCATION | DAMAGE | CONDITION | COMMENTS | RECOMMENDATION | RISK | REMEDIAL YEAR |
|---|------------------------|---------------------------|-------------------|--|---|------|---------------|
| Mooring Pile | Seaward end of Float B | Mechanical | Good | Check in pile that penetrates the creosote layer. The damage is above higher high water. | Ongoing monitoring. | 8 | - |
| Float C | | | | | | | |
| Bull Rail | North end | Missing | Very Poor | Bull rail is missing at the end of the float. This is typical for sea plane floats, but this float does not have correct signage for seaplane use. | Install bull rail to match existing. | 15 | 2025/2026 |
| Mooring Piles | Mid float | Mechanical | Fair to Good | Abrasive damage to piles from float structure through tidal cycles. Creosote layer is intact. | Ongoing monitoring. | 8 | |
| Float H | | | | | | | |
| Deck Boards | General | Mechanical | Fair to Good | Edge distance for hardware insufficient and select boards are cracking and checking at hardware locations. | Ongoing monitoring. | 9 | |
| Deck Boards | General | Mechanical | Fair to Good | Hardware is loose in a few locations. | Ongoing monitoring. | 9 | |
| Mooring Pile Hoop | General | Corrosive | Fair | Bracket and hoop have significant surface corrosion and evidence of steel scaling. | Clean mooring hoop and re-coat | 12 | 2025/2026 |
| Fire Department Floats (Floats E, F, G and Slips F-1 and F-2) | | | | | | | |
| Deck Boards | General | Mechanical/ Biological | Poor to Very Poor | Significant weathering and localized areas of decay. Boards are missing in areas. | Float is at or nearing the end of its service life. Replacement of float structures in their entirety is recommended. | 25 | 2025/2026 |
| Bull Rails | General | Mechanical/ Biological | Poor to Very Poor | | | | |
| Rub Boards | General | Mechanical/ Biological | Poor to Very Poor | | | | |
| Substructure | General | Mechanical/ Biological | Poor to Very Poor | Evidence of biological damage and water ingress | | | |
| Floatation | General | Mechanical/ Biological | Very Poor | Floats are listing significantly, missing floatation in areas, and no longer have freeboards within acceptable tolerances. | | | |
| Connections | General | Mechanical/ Biological | Very Poor | Connection to other floating structures is unconventional and places stress on adjacent structures (floats). | | | |

Appendix C

Marine Infrastructure Checklist

HEROLD ENGINEERING

MARINE STRUCTURAL ASSESSMENT REPORT

BRIDGE NAME GRAPPLER WHARF **LOCATION** BAMFIELD, BC

LENGTH N/A **ROADWAY WIDTH** N/A **CLEARANCE** N/A
No. SPANS N/A **SPAN TYPE** N/A **MAX. SPAN** N/A
POSTED LOAD N/A **YEAR BUILT** 2000-2023 **UTILITIES** N/A

| ITEM | CONSTRUCTION | 25 | | | | | | | | | | | | | | | | | | |
|----------------|----------------------------|-----|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|
| ABUTMENTS | NOT ACCESSIBLE | N/A | | | | | | | | | | | | | | | | | | |
| APPROACH | 183 METERS X 29.0 METERS | G | | | | | | | | | | | | | | | | | | |
| DECKING | 52 X 152 | G | | | | | | | | | | | | | | | | | | |
| VEHICLE GUARD | 102 X 152 | G | | | | | | | | | | | | | | | | | | |
| HANDRAILS | VARIES | G | | | | | | | | | | | | | | | | | | |
| STRINGERS | 89 X 242 | F | | | | | | | | | | | | | | | | | | |
| PILE CAPS | 241 X 305 | F | | | | | | | | | | | | | | | | | | |
| BEARING PILES | SIZE 36 (305MM DIA.) | G | | | | | | | | | | | | | | | | | | |
| CROSS BRACING | 89 X 140 AND 140 X 191 | F-P | | | | | | | | | | | | | | | | | | |
| GANGWAY | 137 METERS X 11.05 METERS | P | | | | | | | | | | | | | | | | | | |
| FLOAT A | 2.79 METERS X 38.56 METERS | G-F | | | | | | | | | | | | | | | | | | |
| FLOAT B | 2.13 METERS X 36.0 METERS | G-F | | | | | | | | | | | | | | | | | | |
| FLOAT C | 1.83 METERS X 30.65 METERS | G-F | | | | | | | | | | | | | | | | | | |
| FLOAT C SLIPS | 1.03 METERS X 4.93 METERS | G | | | | | | | | | | | | | | | | | | |
| FLOAT D | 1.74 METERS X 22.71 METERS | G-F | | | | | | | | | | | | | | | | | | |
| FLOAT D SLIPS | 1.03 METERS X 4.83 METERS | G | | | | | | | | | | | | | | | | | | |
| FLOAT H | 6.1 METERS X 12.2 METERS | G | | | | | | | | | | | | | | | | | | |
| FLOATS E, F, G | VARIES | VP | | | | | | | | | | | | | | | | | | |
| MOORING PILES | SIZE 36 (305MM DIA.) | G-F | | | | | | | | | | | | | | | | | | |

RATING SCALE


- VERY GOOD (VG) – ELEMENT IS IN SERVICEABLE CONDITION WITH NO NOTABLE DETERIORATION. NO REPAIRS ARE REQUIRED.
- GOOD (G) – ELEMENT HAS MINOR AMOUNTS OF SUPERFICIAL DETERIORATION WITH NO NOTED OVERSTRESSING OR STRUCTURAL DAMAGE.
- FAIR (F) – ELEMENT HAS MODERATE AMOUNTS OF DAMAGE WHICH MAY INCREASE RATES OF DETERIORATION LONG TERM. NO NOTED OVERSTRESSING IS OBSERVED. REPAIRS TO PROLONG SERVICE LIFE MAY BE APPLICABLE.
- POOR (P) – ELEMENT HAS SIGNIFICANT AMOUNTS OF DAMAGE OR DETERIORATION. HOWEVER NO OVERSTRESSING IS OBSERVED. THE ELEMENT IS NEARING THE END OF SERVICE LIFE.
- VERY POOR (VP) – ELEMENT IS NO LONGER IN SERVICEABLE CONDITION WITH SIGNIFICANT DAMAGE OR LOSS OF STRUCTURAL CAPACITY. IMMEDIATE REPAIR OR REPLACEMENT IS LIKELY.

REMARKS

2025 LARGE FACILITY. REFER TO APPENDIX B OF ASSESSMENT REPORT FOR DETAILS.

Appendix D Aerial Map

Grappler Wharf



LIST OF OF WHARF COMPONENTS AT GRAPPLER WHARF

'Condition' & 'Risk' columns evaluate all of the bridge components and displays the worst condition value and highest risk value.

| UniqueID | Name | Asset Type | Surface | Condition | Risk | MaintainedBy |
|-----------|-------------|-------------|--------------------------|-----------|------|---------------------------|
| 070100001 | A | Float | Treated Timber | Poor | 16 | Bamfield Parks Commission |
| 070101001 | Approach | Gangway | Treated Timber | Fair | 12 | Bamfield Parks Commission |
| 070100002 | B | Float | Treated Timber | Fair | 15 | Bamfield Parks Commission |
| 07051001 | Boat Launch | Boat Launch | Pre-cast Concrete Panels | Fair | 9 | Bamfield Parks Commission |
| 070100003 | C | Float | Treated Timber | Poor | 15 | Bamfield Parks Commission |
| 07099001 | C-1 | Slip | Treated Timber | Fair | 0 | Bamfield Parks Commission |
| 07099002 | C-2 | Slip | Treated Timber | Fair | 0 | Bamfield Parks Commission |
| 07099003 | C-3 | Slip | Treated Timber | Fair | 0 | Bamfield Parks Commission |
| 07099004 | C-4 | Slip | Treated Timber | Fair | 0 | Bamfield Parks Commission |
| 07099005 | C-5 | Slip | Treated Timber | Fair | 0 | Bamfield Parks Commission |
| 070100004 | D | Float | Treated Timber | Fair | 0 | Bamfield Parks Commission |
| 07099006 | D-1 | Slip | Treated Timber | Good | 0 | Bamfield Parks Commission |
| 07099007 | D-2 | Slip | Treated Timber | Good | 0 | Bamfield Parks Commission |
| 07099008 | D-3 | Slip | Treated Timber | Fair | 6 | Bamfield Parks Commission |
| 030100005 | E | Float | Treated Timber | Very Poor | 12 | Bamfield Fire Department |
| 030100006 | F | Float | Treated Timber | Very Poor | 25 | Bamfield Fire Department |
| 03099009 | F-1 | Slip | Treated Timber | Very Poor | 25 | Bamfield Fire Department |
| 03099010 | F-2 | Slip | Treated Timber | Very Poor | 25 | Bamfield Fire Department |
| 030100007 | G | Float | Treated Timber | Very Poor | 25 | Bamfield Fire Department |
| 070101002 | Gangway | Gangway | Treated Timber | Poor | 16 | Bamfield Parks Commission |
| 030100008 | H | Float | Treated Timber | Good | 12 | Bamfield Fire Department |